

LANDMARK

Specifications

Foundation : Earthquake resistant RCC framed super structure with in fill

bricks/walls.

Elevation : Skilled and quality craftsmanship to make the complex a

symbol of class.

Doors/Windows : Colour Anodised casement (Sliding), Aluminium windows

fitted with grills. Wooden Door frames, Water resistant fulsh

doors with standard fittings.

Flooring : Vitrified tiles in Drawing, Dining and Bedroom. Anti-skid tiles in

toilets.

Fire Fight System : Equipped with efficient and effective fire fighting system.

Wall Finish : Interior-Wall putty, Exterior - Painted with good quality exterior

paint.

Kitchen : Anti-skid Ceramic tiles in floor, Granite counter top with

stainless steel sink & Ceramic tiles upto 2 feet above counter.

Toilet : CP fittings of Jaguar or equivalent brand, wall hung EWC, Wash

Basin & High quality ceramic tiles upto door height.

Elevator : Automatic elevator in each block.

Electrical/Wiring: Concealed wiring with fire resistant ISI grade copper


conductors having provision for adequate points & TV sockets in Drawing & Master bedroom. A.C. points in master bedroom. Protective M.C.B's & elegant modular switches of reputed

brand.

Packages : Internal upgradation available on request at extra cost.


Typical Floor Plan





Area Statement

| Flat No. | Built up Area | Common Area | Super Built up | Total |
|----------|------------------|----------------|-------------------|-------|
| Flat - A | 661 | 93 | 151 | 904 |
| Flat - B | 735 | 103 | 167 | 1005 |
| Flat - C | 872 | 122 | 199 | 1193 |
| Flat - D | 941 | 132 | 215 | 1288 |
| Flat - E | 537 | 75 | 122 | 734 |



LANDMARK

Lifestyle Amenities

Easily Accessible Location

Eye catching Elevation

Landscaped Garden

50% Open Space

Vaastu Friendly Design

Automatic Lifts

20 Premium 2 & 3 BHK Apartments

Air-Conditioned Community Hall

Covered Parking (At extra cost)

Power Back-up for Common Area

CCTV Camera Surveillance

Round the Clock Security Guards*

*to be managed and maintained by the society management committee after delivery.